


DPS-3 Series (Anti-corrision)

PANEL




序号	名称
1	Locking indicator
2	Ouput indicator
3	Pressure unit
4	Main display section
5	Up button
6	Setting button
7	Down button
8	Electric interface
9	Pressure port

SPECIFICATION

Model		DPS-301(Compound)	DPS-310(Positive)
Pressure measure	Range Of Measure	-100kPa~100kPa	-0.100MPa~1.000MPa
	Setting Range	-100kPa~100kPa	0.000MPa~1.000MPa
	Withstand Pressure	500kPa	1.500MPa
	Pressure Type	Non-flammable ,Non-positive gas, Gauge pressure measurement	
	Measure Accuracy	≤±2%f.s.(ambient temperature 25°C)	
	Temperature Error	≤±3%f.s.(t emperature range 0~ 50°C)	
	Measure Pattern	Hysteresis mode Single point mode Window mode	
Port size		External R1/8, NPT1/8, G1/8 option , internal thread M5	
Display	Status Display	LCD display,4-digital measurement value ,unit display ,output status display	
	Display Model	Adjustable backlight ,4 groups of dispaly models	
Input Power	Voltage Range	12~24vdc ±10%	
	Power Consuption	40ma max(non-load)	
Output Signal	Transistor Output	NPN open-collector oupt Output current :80ma max Voltage drop : ≤1v	PNP open-collector oupt Output current :80ma max Voltage drop : ≤1v
	Response Time	Adjustable : 2.5ms、 20ms、 100ms、 500ms、 1000ms、 2000ms	
	Short-circuit Protecdtion	Yes	
Environmetal Resistance	Ip Class	Ip65	
	Ambient Temperature	Operating temperature 0~50°C ,storage temperature -20~60°C	
	Ambient Humidity	Operating humidity 35~ 80%rh	
	Insulation Voltage	1000vac 1min	
	Insulation Resistance	≥50mΩ(500vdc)	
	Shock	Max100m/s ² ,3time seach in 6 directions of x,y,z	
Vibration	Amplitude 1.5mm, 10hz~ 500hz, 2 hours each direction of x,y,z		

ORDERING CODE



1. DPS-3 Series

2. Range

10: -100~100kPa
01: -100~100kPa
16: 0~1600kPa

3. Port

R: R1/8 (M5 female thread)
N: NPT1/8 (M5 female thread)
G: G1/8 (M5 female thread)

4. Output

X: NPN+PNP
Explanation 1: Product single-channel setting,
Optional NPN or PNP output channel,
the black wire is NPN and the white wire is PNP

5. Mounting

M: Panel
N: Panel+shield
Z: L bracket
S: S bracket


QUICK SETTING

Zero point setting




In the measure mode, press **▲** + **▼** button at the same time, until display "0", release the button;
PS: reset range: +/-10%F.S.

key lock and unlock




Lock: in the measure mode, press **▲** + **SET** + **▼** button at the same time until "LOCK ON" shown, release the buttons;
Unlock: in the measure mode, press **▲** + **SET** + **▼** button at the same time until "LOCK OFF" shown, release the buttons.

Easy setup




MOUNTING DIMENSIONS(mm)

Mounting dimensions(mm)








Mounting Bracket

L bracket




S bracket




DPS series digital pressure switch


Panel bracket



Panel mount



Add dust cover installation



Wire dimension

